03500.017593 <u>PATENT</u>

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Hoan Tran
TOSHIFUMI MORITANI)	
	:	Group Art Unit: 2852
Appl. No.: 10/670,243)	
	:	Confirmation No.: 8592
Filed: September 26, 2003)	
	:	
For: IMAGE FORMING APPARATUS)	
INCLUDING A ROTARY MEMBER HAVING	:	
A ⊃ SHAPED CROSS SECTION DRIVE)	
CONNECTING MEMBER	:	
)	
U.S. Patent No.: 7,162,186 B2	:	
)	
Issued: January 9, 2007	:	June 13, 2007

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However,

the Commissioner is authorized to charge any underpayment or credit any overpayment to

Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by

telephone at (202) 530-1010. All correspondence should continue to be directed to our address

given below.

Respectfully submitted,

/William M. Wannisky/

William M. Wannisky Attorney for Patentee Registration No. 28,373

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

Facsimile: (212) 218-2200

WMW:eyw

Form #33 - 2 -

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

7,162,186 B2 PATENT NO.

DATED January 9, 2007

TOSHIFUMI MORITANI Page 1 of 2 INVENTOR(S) :

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE, AT ITEM (57), Abstract:

Line 2, "developing" (second occurrence) should read --develop--.

Line 4, "device." should read --devices.--.

Line 10, "is" (second occurrence) should be deleted.

Lines 12-13, close up the vertical space.

COLUMN 4:

Lines 42-43, close up the vertical space.

Lines 43-44, close up the vertical space.

Line 52, close up the vertical space.

COLUMN 5:

Line 58, "part;" should read --part; and--.

Line 60, "by power" should read --by the power--.

Line 62, "rotated;" should read --rotated, and--.

COLUMN 6:

Lines 1-2, close up the vertical space.

Line 12, "and modules" should read -- and the modules--.

Line 18, "to" should read --on--.

Line 37, "other;" should read --other,--.

Line 38, "second" (second occurrence) should be deleted; and "are" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. 7,162,186 B2

No. of add'l. copies @ 30¢ per page



Staple Here Only! Staple SHINE SAINTERS

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,162,186 B2

DATED: January 9, 2007

INVENTOR(S) : TOSHIFUMI MORITANI Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6 continued:

Line 43, "rotation" should read -- the rotation--.

Lines 44-45, close up the vertical space.

Line 55, "are" should read --is--.

Line 57, "are" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile **PATENT NO.** 7,162,186 B2

No. of add'l. copies @ 30¢ per page

